

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060031	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/05/2016
NAME OF PROVIDER OR SUPPLIER PRESTON HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 4910 HARRIS WOODS BOULEVARD CHARLOTTE, NC 28269		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report of Biennial Construction Survey by Frank Strickland on 08/05/2016: Records indicate that the Preston House I facility, originally submitted for licensure on 06/05/1997, and Preston House II, originally submitted for licensure on 10/21/1999, were combined after a Declaratory Ruling on 10/07/2009 and both licenses were consolidated into a single license as an Adult Care 40-bed Special Care Unit, under the existing license number for Preston House I, LLC. Based on this information, we are requiring the facility to meet the 1996 North Carolina State Building Code, Volume I- General Construction 409 special Institutional Occupancies with (1997 revision). Also, the 1996 Rules for the Licensing of Adult Care Homes and applicable portions of the 2005 Regulations for Adult Care Homes. LICENSED 40 BED SPECIAL CARE UNIT Deficiencies have been cited and a Plan of Correction is required.	C 000		
C 164	Housekeeping and Furnishings-Clean, Repaired SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1-Based on observations, this facility has not maintained interior doors so that they latch and	C 164		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060031	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/05/2016
NAME OF PROVIDER OR SUPPLIER PRESTON HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 4910 HARRIS WOODS BOULEVARD CHARLOTTE, NC 28269		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 164	Continued From page 1 close properly to prevent the passage of smoke. Findings on 08/05/2016: The Attic Storage Room entry door drags on the floor and it not secured at the top door hinge in Preston I Building. 2-Based on observation, the facility has not maintained and serviced the HVAC supply and return air grilles. Findings on 08/05/2016: The exhaust and return-air grilles have excessive particulate build-up located in the Preston I Facility Kitchen.	C 164		
C 166	Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1-Based on observation, the facility has failed to maintain an uncluttered and clean environment in rooms and spaces in the facility. Findings on 08/05/2016: The Attic Mechanical Room that is located in the Preston I Facility has excessive amounts of pipe insulation and related construction debris that are laying all the floor surfaces around the HVAC units in the back corner of the room. This	C 166		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: HAL060031	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 08/05/2016
NAME OF PROVIDER OR SUPPLIER PRESTON HOUSE		STREET ADDRESS, CITY, STATE, ZIP CODE 4910 HARRIS WOODS BOULEVARD CHARLOTTE, NC 28269		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 2 condition could create trip hazards and potentially a fire hazards.	C 166		
C 199	Exhaust Ventilation SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: (1) soiled linen storage; (2) soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities. This Rule is not met as evidenced by: 1-Based on observation, this facility failed to provide an environment in accordance with this Rule by not providing ventilation where odors are generated. This could affect residents and staff by subjecting them to house-keeping odors. Findings on 08/05/2016: The mechanical exhaust fans are not exhausting interior air in the following locations: (a) All of the resident bathrooms in the Preston II Building. (b) All of the staff and guest bathrooms.	C 199		